Customer Quality Clause Update Worksheet

CUSTOMER **Meggitt Defense Systems (Wester Design)**
QC Codes for Suppliers for (WD only)
Revision 6/20/2006

CODE	DESCRIPTION	INSCO DESCRIPTION (IF NEEDED)
A	Western Design Source Inspection	Notify WD QA five days in advance to schedule inspection. Have all documents,dwgs.
B	Government Source Inspection	Notify Gove Rep with copy of P.O. to schedule inspection
C	Certificate of Conformance	One copy with each and every shipment/
D	Material Certifications and Test Reports	Each shipment shall have chemical and physical test reports for each line item
E	Acceptance Test / Dimensional Reports	A 100% DimensionalInspection is required
F	F.O.D	All shipments to verified by Quality for F.O.D before being closed.
M	Marking Requirements	In accordance with drawing requirements "Bag&Tag" apply to packaging
N	Supplemental Q.A. Requirements	Additional WD QA Provision (SQAP)
	Check PO's for: DO, DX, DPAS	